

**DRAPER®**

THE TOOL COMPANY

**VW/AUDI/Saab 900  
SERVICE RESET TOOL**

■ STOCK No.69008

■ PART No.OSR/VAG

**INSTRUCTIONS****05/2006****SPECIFICATION:**

The Draper Tools policy of continuous improvement determines the right to change specification without notice.

Covers vehicles' year 1991 up to June 2000.

**SET UP**

| Switch Position   | Make/Model  |
|---|---|
|    | Audi A3, A4, A6, A8 & 100<br>VW Passat, Golf Mk3 & Sharan   |
|    | VW Polo From 98   |
|    | Audi A3 from 98, A4 from 98, A6 from 98, TT<br>VW Passat B5 |
|    | Audi A4 & A6  |
|    | VW Golf Mk4 & New Beetle                                    |
|    | VW Passat from 97   |
|   | Audi A8   |
|  | VW Sharan From 98   |

Depending on the vehicle's country of origin and year of manufacture it may be necessary to try more than one position to extinguish the service or airbag lights.

| Switch Position   | Function     | Car Model  |
|---|--------------|--|
|  | Oil Service  | All above car models                               |
|  | Inspection 1 | All above car models, except Audi TT               |
|  | Inspection 2 | All above car models, except Audi TT               |
|  | Airbag       | All above car models, except Passat B5 & Sharan 98 |

# INSTRUCTIONS

Since there are various VW, Audi Group models with different communication protocols for different reset functions, carefully read the following instructions to set the 8-pin switch prior to reset. Failure to do this may damage the reader or your vehicle.

There are 8 pins on the switch:

Pin 1-3 Vehicle Make/Model on vehicle set-up table

Pin 4-5 Function Selection

Pin 6-8 Always set to off - switch 6 is for airbag re-set on Saab 900 only

Refer to table 1 and set the vehicle type.

Refer to table 2 and set the desired action.

Switch off the vehicle's ignition and insert the appropriate connector into the vehicle's diagnostic socket (refer to the vehicle manufacturer's handbook or Haynes manual for the correct location).

Switch the vehicle ignition to the 'on' position and switch the reset tool 'start' button to activate the process.

During the reset process, the L.E.D. will flash for a few seconds and will remain 'on' when the reset is complete.

Switch 'off' the vehicle ignition and disconnect the reset tool.

## **OPERATIONAL STEPS FOR RESETTING AIRBAG INDICATOR ON SAAB 900:**

1. Turn vehicle ignition off and insert the reset tool into the vehicle's diagnostic socket.
2. Turn ignition 'ON', but do not start the engine. The green L.E.D. lights on the tool will come on.
3. Set switch 6 at 'ON' position and keep the others at 'OFF' then press 'START' button to reset the airbag in Saab 900 vehicles.
4. Turn vehicle ignition 'OFF' and disconnect the Reset Tool.

**NOTE:** If during the reset process the L.E.D. starts flashing in an unusual manner, this indicates a failure and the process must be repeated. If after the reset operation the green LED flashes for 10 seconds, then stays off for 1 second, flashes for another 10 seconds and remains on - resetting has failed.

**IMPORTANT:** For detailed and concise instructions on the correct use of this tool, refer to the vehicle manufacturer's or relevant Haynes workshop manuals.